

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-013872**Date Inspected:** 06-May-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No			
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006	Component:	OBG				

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

TRIAL ASSEMBLY YARD

ULTRASONIC INSPECTION

OBG SEGMENT 8AE

ABF Report No: UT-8E-031

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Inspection was carried out on hold back weld. Weld identification numbers were.

SEG044*-043 (8AE, D.P to E.P- Cross beam side)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of planar transverse indication.

WELDING INSPECTION REPORT

(Continued Page 2 of 4)

No relevant indications were observed.

ULTRASONIC INSPECTION

OBG SEGMENT 8CE

ABF Report No: UT-8E-036

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Inspection was carried out on hold back weld. Weld identification numbers were.

CA054-006 (8CE, D.P to E.P- Bike path side)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of planar transverse indication.

No relevant indications were observed.

ULTRASONIC INSPECTION

OBG SEGMENT 8AE

ABF Report No: UT-8E-032

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Inspection was carried out on hold back weld. Weld identification numbers were.

SEG048-002, 006 (8AE, D.P to E.P- Bike path side)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of planar transverse indication.

No relevant indications were observed.

ULTRASONIC INSPECTION

OBG SEGMENT 8CE

ABF Report No: UT-8E-035

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Rejectable indications were observed. Inspection was carried out on hold back weld. Weld identification numbers were.

SEG048*-043 (8CE, D.P to E.P- Cross beam side)

WELDING INSPECTION REPORT

(Continued Page 3 of 4)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of planar transverse indication. For more information refer the ABF /CT report dated on 05/05/2010 & 05/06/2010.

ULTRASONIC INSPECTION

OBG SEGMENT 8BE

ABF Report No: UT-8E-033

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Rejectable indications were observed. Inspection was carried out on hold back weld. Weld identification numbers were.

CA051-002, 006 (8BE, D.P to E.P- Cross beam side)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of planar transverse indication. For more information refer the ABF /CT report dated on 05/05/2010 & 05/06/2010.

ULTRASONIC INSPECTION

OBG SEGMENT 7EE

ABF Report No: UT-7E-074

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Rejectable indications were observed. Inspection was carried out on hold back weld. Weld identification numbers were.

CA046-002, 006 (7EE, D.P to E.P- Bike path side)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of planar transverse indication. For more information refer the ABF /CT report dated on 05/05/2010 & 05/06/2010.

ULTRASONIC INSPECTION

OBG SEGMENT 8BE

ABF Report No: UT-8E-034

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10% of OBG components previously accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3 and Detection of Transverse Planar Discontinuities with Significant Flaw Height Dimension Procedure. Rejectable indications were observed. Inspection was carried out on hold back weld. Weld identification numbers were.

CA052-002, 006 (8BE, D.P to E.P- Bike path side)

This QA Inspector performed conventional UT (Ultrasonic Testing) after ABF UT department for detection of

WELDING INSPECTION REPORT

(Continued Page 4 of 4)

planar transverse indication. For more information refer the ABF /CT report dated on 05/05/2010 & 05/06/2010.

Unless otherwise noted, all work observed on this dated appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Utekar,Shrikant	Quality Assurance Inspector
Reviewed By:	Dawson,Paul	QA Reviewer
